

DATE	REVISION
A 17.8.09	B205 UPDATED TO "COMMS ROOM" PLAN UPDATED FOLLOWING FSO SURVEY
B 17.1.11	B238 & B239 CHANGED TO 'MEETING ROOM'
C 21.2.13	CAVITY BARRIER DETAILS UPDATED AS REQUESTED BY FSO
D 15.8.13	UPDATE FOLLOWING WORKS TO B223a & B224
E 7.1.14	UPDATE FOLLOWING WORKS TO INSTALL DOORS IN B224 & ADJACENT CORRIDOR.
F 21.2.14	B216b CAPACITY UPDATED TO 10
G 27.1.15	B241 UPDATED TO 'TRANQUILITY ROOM'. B223a UPDATED TO 'JBA'
H 8.1.16	B238 & B239 UPDATED TO 'TUTORIAL'
J 19.9.16	EXTINGUISHER POSITIONS & TYPES UPDATED.
K 20.2.18	B208 & B220 UPDATED TO 'VACANT (Staff)'
L 20.6.18	B206 UPDATED TO 'STAFF'
M 11.12.18	B208, B220 & B223a UPDATED TO 'STAFF'
N 15.4.19	B216b UPDATED TO 'STORE/WORKSHOP'

THIS FIRE SAFETY PLAN IS GENERALLY BASED ON INFORMATION PROVIDED BY BU'S FIRE SAFETY OFFICER. IT IS THE RESPONSIBILITY OF ALL USERS OF THIS PLAN TO CHECK THE INFORMATION PROVIDED TO CONFIRM THE EXACT POSITIONS OF THE FIRE SAFETY EQUIPMENT, CAVITY BARRIERS ETC.

SECOND FLOOR FIRE PLAN

BOURNEMOUTH HOUSE

BH/FP/4N

SCALE 1:200 at A3
JANUARY 2004



- B2S1 Existing wheelchair refuge zone
- Existing fire resisting construction 30 min.
- Existing cavity barrier
- Denotes line of fire resisting construction required
- ⊙ Existing dry riser outlet
- ← Denotes directional arrow on existing fire exit sign
- ▲ Existing 6 litre P50 foam fire extinguisher
- Existing call point – manual
- ⬠ Existing audible warning device – bell
- ⬠ Existing visual warning device
- ⬠ Existing smoke detector
- ⬠ Existing exit sign – internally illuminated
- ⬠ Existing emergency lighting luminaire – self contained
- S12 Existing fire action sign – general
- S22 Existing fire exit sign
- FRSC Existing self closing device fitted to fire-resisting door