



DATE	REVISION
A 1.11.05	ROOMS D136B & D157a CREATED. EVAC CHAIRS ADDED
B 20.1.06	"CAVITY BARRIER REQUIRED" ADDED
C 12.9.06	ROOMS D147, D167 UPDATED FOLLOWING MINOR WORKS. D137 REMOVED
D 27.3.08	"S22" SIGNS ADDED. BU LOGO UPDATED
E 27.7.10	GENERAL UPDATE FOLLOWING FSO SURVEY
F 3.2.11	GENERAL UPDATE FOLLOWING FSO SURVEY
G 23.9.11	D165 CHANGED FROM PC SUITE TO SEMINAR ROOM
H 31.8.12	D165 CHANGED TO ST POST GRAD OFFICE, D166 ALLOCATED TO ST.
J 22.1.13	D136a CHANGED TO RESOURCE & D136b CHANGED TO MEETING ROOM
K 2.6.15	D152 & D154 DOOR POSITIONS CORRECTED
L 21.9.16	OPEN ACCESS BUILDING OUTLINE REMOVED FOLLOWING DEMOLITION. ROOF OUTLINE UPDATED. FIRE PANEL, PIB & REFUGE INTERCOM ADDED. EXTINGUISHER POSITIONS & TYPES UPDATED.
M 2.6.17	D152 UPDATED TO 'VACANT'
N 15.1.18	D152 UPDATED TO 'STAFF'
P 7.1.19	D103 UPDATED TO 'VACANT'
Q 19.2.20	D107, D123, D143, D144 & D159 UPDATED TO 'VACANT'.
R 29.7.21	D115 UPDATED TO 'STAFF'.
S 24.11.22	D103, D107, D123, D143, D144 & D159 UPDATED TO 'STAFF'.

THIS FIRE SAFETY PLAN IS GENERALLY BASED ON INFORMATION PROVIDED BY BU'S FIRE SAFETY OFFICER. IT IS THE RESPONSIBILITY OF ALL USERS OF THIS PLAN TO CHECK THE INFORMATION PROVIDED TO CONFIRM THE EXACT POSITIONS OF THE FIRE SAFETY EQUIPMENT, CAVITY BARRIERS ETC.

## FIRST FLOOR FIRE PLAN

DORSET HOUSE

DH/FP/3R

SCALE 1:200 at A3  
AUGUST 2005



Key to Fire Symbols (existing)

- D1S1 Refuge zone
- Existing fire resisting construction 30 min.
- Existing Evac chair
- Existing emergency lighting luminaire
- Existing 6 litre P50 foam fire extinguisher
- Existing call point - manual
- Existing audible warning device
- Existing visual warning device
- Existing smoke detector
- S12 Existing fire action sign - general
- S22 Existing fire exit sign
- Existing exit sign - internally illuminated
- ← Denotes directional arrow on existing fire exit sign

