


FR /cavity barrier lines are based on a survey & remedial works carried out by Oak Leaf & Nene Valley Fire. Some doors may have "Fire Door" signage attached but be within a wall that is not shown as FR on this plan. This is because some walls have been assessed as non-FR compliant during the survey & remedial works. Therefore, these doors & walls should be regarded as non-FR.

- Key to Fire Symbols**
- Existing dry riser outlet
  - Existing fire resisting construction 30 min.
  - Existing cavity barrier
  - Existing wheelchair refuge zone
  - Existing 6 litre P50 foam fire extinguisher
  - Existing call point - manual
  - Existing emergency lighting luminaire
  - Existing visual warning device
  - Existing smoke detector
  - Existing combined smoke detector & sounder
  - Existing exit sign - internally illuminated
  - Existing fire exit sign
  - Existing audible warning device
  - Existing emergency door release call point - manual
  - Denotes directional arrow on existing fire exit sign
  - Existing fire action sign - general
  - Existing self closing automatic release
  - Existing self closing device fitted to fire-resisting door
  - Existing pushbar door ironmongery
  - Area covered by existing emergency lighting



DATE	REVISION
A 27.11.08	P221 ALTERED TO FORM SOUND BOOTHS FOR DEC
B 29.9.09	P218 DIVIDED INTO TWO STORES. UPDATE TO SHOW WORKS TO INSTALL DEC SOUND BOOTHS PHASE 3 - P211, P219 & P220. P215c & P215d COMBINED WITH P215a & P215b. P201 CONVERTED TO DEC NETWORK LAB.
C 23.3.10	WC LAYOUTS UPDATED FOLLOWING REFURBISHMENT
D 28.9.10	UPDATE FOLLOWING FSO SURVEY & MINOR WORKS
E 30.11.10	P223b UPDATED TO STORE
F 23.2.11	UPDATE FOLLOWING FSO SURVEY
G 29.9.11	ALTERATIONS TO P222 - P225 AREA FOR DEC.
H 16.11.11	ALTERATIONS TO P217 FOR DEC.
J 11.1.12	P106 UPDATED TO "CREATIVE LAB"
K 5.12.12	NEW PC LABS FORMED (P201, P213, P213a, P223 & P232). P225, P226, P227, P229 & P230 REFURBISHED/MODIFIED, OFFICE P231 CREATED, ALL ROOMS RENUMBERED.
L 18.2.13	P236 CHANGED FROM PRINT ROOM TO STORE.
M 1.11.13	UPDATE FOLLOWING PHASE 2 OF FLOOR REFURBISHMENT
N 7.2.14	NOTE ON REQUIRED REMEDIAL WORKS ADDED.
P 24.3.15	UPDATE FOLLOWING REMEDIAL FIRE SAFETY WORKS TO P231.
Q 16.9.15	VARIOUS ROOM NAMES UPDATED
R 27.9.16	EXTINGUISHER POSITIONS & TYPES UPDATED
S 28.9.17	P221 CHANGED TO "TEACHING ROOM" & P221a DOOR POSITION & CAVITY BARRIER UPDATED.
T 4.4.19	UPDATE FOLLOWING SURVEY & WORKS TO CAVITY BARRIERS
U 29.7.20	P216, P222 & P228 CHANGED TO "TEACHING ROOMS".
V 4.8.21	TEACHING ROOM MOVED FROM P216 TO P225

THIS FIRE SAFETY PLAN IS GENERALLY BASED ON INFORMATION PROVIDED BY BU'S FIRE SAFETY OFFICER. IT IS THE RESPONSIBILITY OF ALL USERS OF THIS PLAN TO CHECK THE INFORMATION PROVIDED TO CONFIRM THE EXACT POSITIONS OF THE FIRE SAFETY EQUIPMENT, CAVITY BARRIERS ETC.

## SECOND FLOOR FIRE PLAN

POOLE HOUSE:  
MAIN BLOCK

PH/M/FP/3V

SCALE 1:200 at A3  
NOVEMBER 2007

