



DATE	REVISION
A 4.9.06	SS02-8 AMENDED FOLLOWING WORKS TO FORM TEACHING ROOMS PLAN REDRAWN FOLLOWING SURVEY.
B SEPT.08	FLOOR PLAN UPDATED FOLLOWING RECLAD & FULL SURVEY, AS ROOMS VACATED FOLLOWING MOVE TO SH 2nd FLOOR.
C AUG.09	PARTITION & DOOR UPGRADED BETWEEN LOBBY & STAIR 1
D 14.12.10	UPDATE FOLLOWING MAJOR REFURBISHMENT
E 2.5.12	UPDATE FOLLOWING CONSTRUCTION OF SS07
F 20.8.13	UPDATE FOLLOWING CONSTRUCTION OF SS08
G 15.3.16	PARTITION LAYOUT MODS TO SUIT NEW SHARED OCCUPANCY OF FLOOR BY ESTATES & F&P, EMERGENCY LIGHT POSITIONS UPDATED FOLLOWING INSTALL OF NEW LED LIGHTING SYSTEM. REMOVAL OF TEA ROOM DOOR.
H 26.9.16	EXTINGUISHER POSITIONS & TYPES UPDATED
J 16.2.18	LAYOUT ALTERATIONS TO SUIT F&P EXPANSION



- Key to Fire Symbols
- Existing fire resisting construction 30 min.
 - Existing dry riser inlet
 - Existing wheelchair refuge zone
 - Existing call point - manual
 - Existing 6 litre P50 foam fire extinguisher
 - Existing exit sign - internally illuminated
 - Existing emergency lighting luminaire
 - Existing pushbar door ironmongery
 - Guarding handrail
 - Existing electro mechanical lock
 - Existing audible warning device
 - Existing visual warning device
 - Existing smoke detector
 - Existing heat detector
 - Existing fire action sign - general
 - Existing fire exit sign
 - Existing emergency door release call point - manual

FIFTH FLOOR
FIRE PLAN

STUDLAND HOUSE

SH/FP/7J

SCALE 1:200 at A3
JANUARY 2004

