




- Key to Fire Symbols
- W2S1 Existing wheelchair refuge zone
 - Existing fire resisting construction 30 min.
 - ▲ Existing 6 litre P50 foam fire extinguisher
 - ☐ Existing call point – manual
 - ☒ Existing emergency lighting luminaire
 - ⚠ Existing audible warning device
 - ⚠ Existing visual warning device
 - S Existing smoke detector
 - SCA Existing self closing automatic release
 - S12 Existing fire action sign – general
 - S22 Existing fire exit sign
 - ☒ Existing exit sign – internally illuminated



DATE	REVISION
A 28.3.08	PLAN UPDATED FOLLOWING FSO'S SURVEY
B 10.9.08	PLAN UPDATED FOLLOWING FSO'S SURVEY
C SEPT. 10	ROOMS W238-240 COMBINED TO FORM PC LAB.
D 7.12.10	W221 & W222 UPDATED TO SHOW ROOM NUMBERS AS ON SITE
E 11.1.12	UPDATE FOLLOWING VARIOUS ALTERATIONS FOR THE MS - ROOM NUMBERS REVISED TO SUIT
F 24.8.12	W223 & W224 COMBINED TO FORM SINGLE ROOM
G 22.5.13	EXTINGUISHER POSITIONS UPDATED FOLLOWING FSO'S SURVEY
H 21.10.13	UPDATE FOLLOWING WORKS TO FORM W241-2
J 15.8.14	WALL BETWEEN W217 & W218 UPDATED TO SHOW CORRECT POSITION
K 12.8.15	MINOR UPDATES FOLLOWING FSO'S SURVEY
L 11.2.16	W242 CHANGED FROM STAFF ROOM TO STAFF FOLLOWING FMC SURVEY RETURN DEC. 2015.
M 3.5.16	UPDATE TO CAVITY BARRIERS FOLLOWING REQUEST FROM FSO
N 26.9.16	EXTINGUISHER POSITIONS & TYPES UPDATED
P 18.5.18	W233 UPDATED TO 'PPS SUITE'
Q 30.11.18	W236 UPDATED TO 'HOT DESKS'
R 14.10.19	W217 UPDATED FOLLOWING REFURBISHMENT
S 19.2.20	W236 UPDATED TO 'RESOURCE'

THIS FIRE SAFETY PLAN IS GENERALLY BASED ON INFORMATION PROVIDED BY BU'S FIRE SAFETY OFFICER. IT IS THE RESPONSIBILITY OF ALL USERS OF THIS PLAN TO CHECK THE INFORMATION PROVIDED TO CONFIRM THE EXACT POSITIONS OF THE FIRE SAFETY EQUIPMENT, CAVITY BARRIERS ETC.

SECOND FLOOR
FIRE PLAN

WEYMOUTH HOUSE

WH/FP/3S

SCALE 1:200 at A3
11th JANUARY 2006

